


CHECK WIRE SIZE TO INSURE FULL POWER

Minimum Size copper wire For Full Power										
	0 - 50 Feet		50 - 100 Feet		100 - 200 Feet		200 - 300 Feet		300 - 400 Feet	
Motor HP	115V	230V	115V	230V	115V	230V	115V	230V	115V	230V
1/2 HP	12	-	8	-	6	-	4	-	4	-
3/4 HP	12	14	8	10	6	10	4	10	3	6
1 HP	10	12	8	10	4	10	3	8	2	6
1-1/2 HP	8	12	6	8	3	8	1	6	1/0	4
R-11/98	Maximum Voltage drop 4% for Full power									



Important Lubrication Information

All three fittings must be well greased at all times. ALSO teeth of main gear must have heavy grease at all times.

-NOTICE- DO NOT USE THIS UNIT AS A LOAD SUPPORTING BEARING